

ID #	Street Number	Street Name	Evaluation	Construction Date	Date Source	Materials	Architectural Value	Associative Value	Contextual Value	Recorders	Date	Additional Resources	Within HCD Boundary
B1005	5	Bank Street	4	Between 1976 and 20	City of Ottawa. GeoOttawa [aerial photo]. 1976 and 2002. Accessed November 2020. http://maps.ottawa.ca/geoOttawa/	Brick, metal siding, metal roof	Factors contributing to compatibility (not currently protected): 1 storey; compact form; front gable roof.	Currently unknown.	Backs onto cemetery and Keith Boyd Museum.	MTBA	2020-11-01	N/A	Yes
B1008	8	Bank Street	1	1911	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Asphalt shingles, wood/vinyl siding, wood porch and trim, concrete foundation	2 storeys; hipped roof; compact form; well detailed wood front porch; large windows with large contrasting sills; transom windows above front door and ground level windows.	Currently unknown.	Backs onto the Castor River; overlooks cemetery; medium front setback; contributes to its streetscape; mature trees.	MTBA & CW	2018-10-01		Yes
B1010	10	Bank Street	1	1911	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. H. Belden & Co. Illustrated Historical Atlas of the Counties of Stormont, Dundas and Glengarry, Ontario. Toronto: H. Belden & Co. 1879. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Pressed metal shingles, wood sunroom and windows, stucco wall finish, concrete columns and lintels	2 ½ storey; porch with two groups of three classical style columns and balustrades; sunroom above porch; dormer windows; use of "Boyd Block" artistic concrete blocks and columns, pressed metal roof.	Originally owned by the Warner family, then Flemings after 1921.	Backs onto the Castor River; overlooks Cemetery; medium front setback; contributes to its streetscape; mature trees.	MTBA & CW	2018-10-01		Yes
B1012	12	Bank Street	1	1911	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Metal hip roof, faux stone stucco walls, asphalt shingles.	2 ½ storeys; hipped roof with dormer; porch with hipped roof and fluted columns; and decorated with quoins and lintel; faux stone finish; (highly modified).	Previously owned by James Keays (one of the first settlers, Municipal Clerk in 1842, Reeve in 1852, County Registrar, second teacher in Russell, owned 900 acres in Russell).	Backs onto the Castor River; overlooks the cemetery; contributes to its streetscape; medium front setback; mature trees.	MTBA & CW	2018-10-01	Belden, H. Illustrated Historical Atlas of the Counties of Stormont, Dundas and Glengarry, Ontario. (H. Belden & Co. 1879); Stanley, Wendell M. From Swamp and Shanty. Ottawa:	Yes
B1014	14	Bank Street	4	1983	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; Ibid. 2002.	Brick, board and batten wood siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 storey; Dutch gable roof; size/shape and placement of windows; two-car garage.	Currently unknown.	Backs onto Castor River; medium front setback; contributes to its streetscape.	MTBA	2018-12-01		Yes

B1016	16	Bank Street	4	1976	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; Ibid. 2002.	Brick, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 storey; gable roof; bay window; chimney.	Currently unknown.	Backs onto Castor River; "sideways" orientation on lot; medium front setback.	MTBA	2018-12-01		Yes
B1018	18	Bank Street	3	1976	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; Ibid. 2002.	Brick siding and chimney, board and batten wood siding, asphalt shingles	1 storey; front gable roof; decorative brickwork; stairs and balustrade leading to recessed entrance.	Currently unknown.	Backs onto Castor River; medium front setback; contributes to its streetscape.	MTBA	2018-12-01		Yes
B1020	20	Bank Street	4	1990	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Asphalt shingles, vinyl/metal siding	Factors contributing to compatibility (not currently protected): 2 storeys; front and side gable roof with shed roof; porch with columns supporting side gable roof; bow window.	Currently unknown.	Backs onto Castor River; large front setback.	MTBA	2018-12-01		Yes
B1022	22	Bank Street	4	1987	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Half timbering with stucco, asphalt shingles	Factors contributing to compatibility (not currently protected): 2 storeys; half hip (jerkinhead) roof with intersecting gable covering two-car garage and breezeway; size and placement of windows within half-timbers arrangement; chimney with half-timbering; finial/vent over garage	Currently unknown.	Backs onto Castor River; large front setback; mature trees; contributes to its streetscape.	MTBA	2018-12-01		Yes
B1024	24	Bank Street	2	1905	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Siding, wood trim	2 storeys; front gable roof; front porch with balustrade and columns supporting gable roof; front door with side lites; bow window; size/shape of windows and their shutters; older board and batten shed/outbuilding (pre-1945) only somewhat visible from the public realm.	Currently unknown.	Backs onto Castor River; large property with large setbacks; secluded corner lot; mature trees.	MTBA	2018-12-01		Yes
G5008	8	Craig Street	2	1905	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Metal siding, metal and asphalt shingles	2 storeys; hipped roof; small front porch with balustrade and columns supporting a shed roof; compact form; size and location of windows.	Currently unknown.	Small front setback; contributes to its streetscape; mature trees.	MTBA	2019-03-01		Yes
G5012	12	Craig Street	2	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Siding, asphalt shingles	2 storeys; hipped roof; large porch.	Currently unknown.	Small front setback; side yard; contributes to its streetscape; mature trees.	MTBA	2019-03-01		Yes

G5013	13	Craig Street	2	1895	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Metal roof, wood shingle siding and wood lap siding	2 storeys; front porch with columns; gable and shed roofs on home; highly modified; outbuilding/garage with loft and hoist.	Currently unknown.	Prominent location on main thoroughfare.	MTBA, VD & LP	2018-10-01		Yes
G5014	14	Craig Street	2	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Metal siding, metal shingles	2 storeys; hipped roof; size and location of windows; small front porch with balustrade and columns supporting hipped roof.	Currently unknown.	Small front setback; contributes to its streetscape.	MTBA	2019-03-01		Yes
G5015	15	Craig Street	4	1992	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; Ibid. 2002.	Vinyl siding, asphalt shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 1 storey; compact form; side gable roof which extends over front porch; chimney.	Currently unknown.	Backs onto school grounds; large front setback, with mature trees; contributes to its streetscape.	MTBA	2019-01-01		Yes
G5021	21	Craig Street	4	1970	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. RCAF. S(30) RR2118 408(R) [aerial photo]. 1960. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Brick, asphalt shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 1 storey; side gable roof; bay window.	Currently unknown.	Backs onto school grounds; large front setback, with mature trees.	MTBA	2019-01-01		Yes
G5022	22	Craig Street	1	1916 (1920 Barn)	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Metal roof, brick (likely Russell brick), wood trim and detailing	2 ½ storeys; hipped roof with dormer; size and location of windows; front porch with full height brick columns supporting balcony with wood balustrade, wood columns and roof; large contrasting lintels and sills; decorative storm doors; transom window; barn with corrugated siding, hay loft, hoist, sliding door; brick walls.	Barn said to be moved from Finch, Ontario.	Prominent location on main thoroughfare; medium front setback; large side setbacks; barn in rear yard; contributes to its streetscape; garden with mature trees.	MTBA, VD & LP	2018-10-01		Yes
G5027	27	Craig Street	3	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Siding, metal roof, asphalt shingles on canopy	2 storeys; front gable roof; compact form; front porch with balustrade and shed roof.	Currently unknown.	Small front setback; backs onto school grounds; contributes to its streetscape.	MTBA	2019-03-01		Yes

G5028	28	Craig Street	3	1964	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Brick, asphalt shingles	1 storey; side gable roof; bay window; front deck and balustrade.	Currently unknown.	Medium front setback; mature trees.	MTBA	2019-03-01		Yes
G5030	30	Craig Street	4	1995	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018.	Vinyl siding, asphalt shingles	Factors contributing to compatibility (not currently protected): Factors contributing to compatibility (not currently protected): 1 storey; side gable roof; front gable above front windows; hipped roof garage.	Currently unknown.	Medium front setback.	MTBA	2019-03-01		Yes
G5031	31	Craig Street	4	2015	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 2014. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Wood/vinyl siding, stone veneer, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 storey; hipped roofs; compact form.	Currently unknown.	Large front setback; backs onto school grounds.	MTBA	2019-03-01		Yes
G5032	32	Craig Street	2	1941	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Metal roof, Red brick chimney, vinyl siding, wood porch	1 ½ storeys; side gable roof; compact form; small porch with gable; symmetrical façade.	Currently unknown.	Located on main thoroughfare; medium front setback; contributes to its streetscape.	MTBA, VD & LP	2018-10-01	Mikel, Robert. <i>Ontario House Styles: The Distinctive Architecture of the Province's 18th and 19th Century Homes</i> . Toronto: James Lorimer, 2004.	Yes
G5033	33	Craig Street	4	2016	Municipal Property Assessment Corporation (MPAC) - Accessed April, 2019. City of Ottawa. GeoOttawa [aerial photo]. 2014. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; <i>ibid.</i> 2017.	Wood/vinyl siding, stone veneer, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 storey; hipped roofs; compact form.	Currently unknown.	Large front setback; backs onto school grounds.	MTBA	2019-03-01		Yes
G5034	34	Craig Street	4	1990	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; <i>ibid.</i> 2002.	Vinyl siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 2 storeys; gable roofs; bow window.	Currently unknown.	Medium front setback; mature trees; contributes to its streetscape.	MTBA	2019-03-01		Yes
G5035	35	Craig Street	3	1971	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Brick, asphalt shingles, concrete foundation	1 storey; side gable roof; bay window.	Currently unknown.	Large front setback; lot backs onto schoolyard; mature trees.	MTBA	2019-03-01		Yes
G5036	36	Craig Street	4	2004	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 2002. Accessed October	Vinyl siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 2 storeys; gable roofs.	Currently unknown.	Medium front setback; contributes to its streetscape.	MTBA	2019-03-01		Yes

G5038	38	Craig Street	3	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.; City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Metal/vinyl siding, asphalt shingles	2½ storeys; hipped roofs with dormer; small front porch with balustrade and shed roof.	Currently unknown.	Small front setback and large side setback; prominent corner lot on main thoroughfare; contributes to its streetscape.	MTBA	2019-03-01		Yes
G5039	39	Craig Street	3	1960	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Wood/vinyl siding, stone veneer, asphalt shingles	1 storey; side gable roof; picture windows.	Currently unknown.	Large front setback; lot backs onto schoolyard, with mature trees.	MTBA	2019-03-01		Yes
G5043	43	Craig Street	3	1952	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. Canadian Government. A19865-219 [aerial photo]. 1967.	Asphalt shingles, stucco, board and batten siding, vinyl siding (garage)	1½ storeys; overall massing and shape of the home typical of wartime houses; steep side gable roof; location/size of windows.	Currently unknown.	Located on main thoroughfare; backs onto school grounds; mature trees.	MTBA, VD & LP	2018-10-01		Yes
G5049	49	Craig Street	1	1910 (1978 detached garage)	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Russell Historical Society. "Russell House Tour" [walking tour script].	Metal roof, asphalt shingles, Russell brick, white brick, vinyl/wood siding, concrete foundation.	2 ½ storeys; hipped roof with dormers and chimney; large contrasting lintels and sills; size and location of windows; Russell brick walls and quoin detailing.	Built for W.R Craig for whom Craig Street was named; Dr. MacDougall lived here from 1939-1949.	Prominent location on main thoroughfare; backs onto school grounds; overlooks McDougall Park.	MTBA, VD & LP	2018-10-01	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Yes
G5050	50	Craig Street	1	1930-1940	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Limestone sourced locally and from Madoc, Ontario	Stone cairn with metal plaque honouring Dr. MacDougall; dry stone arch bridge (constructed in 2009) considered "the first of its kind in a public park in Canada";	Oldest park in the Township; created by the Township of Russell Horticultural Society and Dr. MacDougall who planted over 100 trees; Arthur Fraser who built the stone cairn and original cedar footbridge; John Shaw-Rimmington who in 2009 built the dry stone footbridge which replaced the cedar	Prominent corner location on main thoroughfare; mature trees; key public property.	MTBA	2019-03-01		Yes
G5053	53	Craig Street	3	1880	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. Canadian Government. A19865-219 [aerial photo]. 1967.	pressed metal roof, smaller asphalt roof, metal siding	1 ½ storeys; L-shape plan; gable roofs; front porch with shed roof; small double hung windows; pressed metal roof.	Relocated from another site between 1945 and 1967.	Prominent location on main thoroughfare; backs onto school grounds; large property with large setbacks; mature trees.	MTBA, VD & LP	2018-10-01		Yes
G5062	62	Craig Street	2	1916	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1888 # 1-14-11-2025-72-14"	Metal roof, siding, stone foundation.	2 ½ storeys; hipped roof with dormers; double hung windows; small porch with balustrade and columns supporting shed roof.	Currently unknown.	Prominent location at bend in the road along main thoroughfare; unusual orientation diagonal to the street reflects historic street layout; small wedge-shaped front setback; mature	MTBA, VD & LP	2018-10-01		Yes

G5066	66	Craig Street	3	Between 1945 and 1967	Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. Canadian Government. A19865-219 [aerial photo]. 1967.	Brick, vinyl/metal siding, asphalt shingles	2 storeys; hipped roofs; size and location of windows.	Currently unknown.	Medium setback; mature trees.	MTBA	2019-03-01		Yes
G5067	67	Craig Street	2	1920	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Siding, metal roof	2 ½ storeys; hipped roof with rear dormer and chimney; front porch with balustrade and columns supporting hipped roof; size and location of windows; wood frame around windows.	Associated with the re-routing of Mill Street and Craig Street.	Backs onto the Castor River; unusual orientation reflects the changes in street layout; large front setback; mature trees.	MTBA	2019-03-01	Canadian Government. A19865-219 [aerial photo]. 1967. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca	Yes
G5069	69	Craig Street	2	1935	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. Canadian Government. A19865-219 [aerial photo]. 1967.	Metal roof, board and batten wood siding, stone chimney	2 storeys; gable roof; chimney; size and placement of windows; porch with slender columns.	Currently unknown.	Backs onto Castor River; prominent location on main thoroughfare; orientation reflects historic street layout; mature trees.	MTBA, VD & LP	2018-10-01		Yes
G5073	73	Craig Street	4	1988	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa	Brick, vinyl siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 storey; compact form; gable roofs.	Currently unknown.	Backs onto the Castor River; large wedge shaped lot; prominent location on main thoroughfare; small front setback.	MTBA	2019-03-01		Yes
G5074	74	Craig Street	1	1860 (1900 shed)	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M. From Swamp and Shanty. Ottawa: Runge Press, 1988	Brick (possibly Russell Brick), wood trim, standing seam metal roof.	2.5 storeys; T-shape plan; side gable roofs with multiple front gable dormers; symmetrical front façade, three bays; segmental arched window opening and round arched attic window; size and location of windows; wood detailing including 'gingerbread' decorative wood fascias; pointed finials; brick walls.	Richard Helmer (builder and son of John Helmer who owned Russell's first brick yard)	Significantly larger lot than surrounding properties; large front setback; mature trees.	MTBA	2018-10-01		Yes
G5078	78	Craig Street	2	Between 1945 and 1967	Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. Canadian Government. A19865-219 [aerial photo]. 1967.	Boyd Block concrete block, asphalt shingles, concrete foundation	1 storey; compact form; hipped roof with chimney; size and location of windows; large contrasting sills and lintels; cantilevered entrance canopy; entrance stairs and balustrade; "Boyd Block" concrete masonry walls.	Currently unknown.	Medium front setback; mature trees.	MTBA	2019-03-01		Yes
H3439	439	Church Street	1	1851	Stanley, Wendell M. From Swamp and Shanty. Ottawa: Runge Press, 1988	N/A	Variety of slab and obelisk shaped tombstones; bordered by shrubs and a picket fence.	Purchased by the Trustees of St. Paul's Methodist Church in 1867; contains the graves of some of the village's early settlers including Nehemiah Pillar (1851, oldest grave) and	Backs onto two streets; gully runs through the centre of the property; mature trees; key public property.	MTBA	2018-12-01		Yes

H3449	449	Church Street	4	1992	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 2 storeys; gable roofs; small front porch.	Currently unknown.	Corner property with large setbacks and mature trees; contributes to its streetscape.	MTBA	2018-12-01		Yes
H3453	453	Church Street	4	1991	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Brick, siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 storey; long side gable roof with front gable over entrance and bow window; small windows with shutters; vertical pattern of alternating red brick and white siding to break up the façade; recessed entrance; two-car garage.	Currently unknown.	Large front setback; mature trees; contributes to its streetscape.	MTBA	2018-12-01		Yes
H3455	455	Church Street	2	1913 (other sources show 1949)	Tweedsmuir History. Russell Village Women's Institute, organized December 1st, 1936. Edited by G. E. McCaffrey. Russell, 1967; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	"Boyd Block" CMU, wood siding and trim, asphalt shingles	1 ½ storeys; hipped roof with dormers; chimney; compact form; rare example of polychromatic façade of exposed aggregate Boyd Block (concrete masonry units) in ashlar pattern; symmetrical façade; large windows with period wood storms.	Built by C.E. McCaffrey.	Backs onto the Castor River; large front and side setbacks.	MTBA, CW & KM	2018-10-01	Gillespie, Ann. "Early Development of the 'Artistic' Concrete Block: The Case of the Boyd Brothers." Bulletin of the Association for Preservation Technology 11, no. 2 (1979): 30-53.	Yes
H3459	459	Church Street	2	1908	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Brick (likely Russell brick), asphalt shingles, vinyl siding, metal roofing	2 storeys; hipped roof; segmentally arched window and door openings; red brick with grey masonry keystones above upper level windows; brick façade added after 1908.	Currently unknown.	Medium front setback; mature trees.	MTBA, CW & KM	2018-10-01		Yes
H3463	463	Church Street	1	1890	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Wood trim, siding, asphalt shingles	2 storeys; steeply pitched gable roof with dormers; L-shaped plan typical of the Ontario Gothic Cottage; size and placement of windows; highly modified.	Currently unknown.	Backs onto the Castor River; medium front setback; large side setbacks; mature trees.	MTBA, CW & KM	2018-10-01		Yes
L8003	3	Mill Street	1	Between 1908 and 1945	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Brick (likely Russell brick), siding, pressed metal roof	2 ½ storeys; hipped roof with rear dormer and chimney; segmentally arched window openings; size and location of windows; bay window; brick walls.	Associated with the re-routing of Mill Street and Craig Street.	Backs onto the Castor River; unusual orientation reflects the changes in street layout; prominent corner location at a bend in the road along main thoroughfare; mature trees.	MTBA	2019-03-01	Canadian Government. A19865-219 [aerial photo]. 1967. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018.	Yes
L8014	14	Mill Street	2	Between 1967 and 1976	Canadian Government. A19865-219 [aerial photo]. 1967. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Brick, metal siding	1 storey; brick.	Upper Canada District School Board; previous school was built on this property.	Large front and exterior side setbacks; large open greenspace behind school building including 2 soccer fields and multiple clusters of mature trees; playgrounds; accessible from 3 streets.	MTBA	2019-03-01		Yes

L8018	18	Mill Street	2	1883 (1910 shed)	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Siding, asphalt shingles, wood trim	1 ½ storey; compact form; front gable roof; small front porch with balustrade and two columns supporting a gable roof; size and placement of window openings.	Currently unknown.	Side yard faces school grounds; medium front setback; contributes to its streetscape; mature trees.	MTBA	2018-12-01		Yes
L8021	21	Mill Street	2	Before 1908, (other sources show 1999)	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Siding, asphalt shingles, wood trim, concrete foundation.	1 ½ storeys; side-gable roof with centre gable over door; T-shape plan typical of the Ontario "Gothic Cottage".	Currently unknown.	Backs onto Castor River; large wedge-shaped lot; large front setback; mature trees.	HH & MTBA	2018-10-01		Yes
L8029	29	Mill Street	3	1977	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa	Stone veneer, wood trim, asphalt shingles	1 storey; long side gable roof.	Currently unknown.	Backs onto Castor River; mature trees; prominent location at a bend in the road; large front setback.	MTBA	2018-12-01		Yes
L8031	31	Mill Street	1	1871 (attached garage 1900); other sources show before 1861	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Russell Historical Society. "Russell House Tour" [walking tour script]. 2014.	Siding, metal shingles, asphalt shingles	Tall 2 storeys; gable roof; porte cochère entrance with gable roof; bay window; (highly modified).	Built by Richard Helmer (Post Master and Brick Maker); a mill, swing bridge, and the first brick yard from 1864 were historically located on this property; at one time there was a swing bridge to the other side of the river where the house was historically.	Large property on peninsula at the bend in the Castor River; large front setback at bend in the road; mature trees.	HH & MTBA	2018-10-01	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Yes
L8035	35	Mill Street	1	1860	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Russell Historical Society. "Russell House Tour" [walking tour script].	Metal roof, siding, wood trim, stone foundation.	2 storeys; gable roof; L-shaped plan typical of Ontario "Gothic Cottage"; double hung windows; bay window with balcony above; wood balustrades; extensive "gingerbread" detailing.	Part of the 200 acre property given to John Mattice in 1828; also owned by Frank Kenny; Doug Warner and the Sherwood family.	Backs onto the Castor River; prominent location at bend in the road; medium front setback; mature trees.	HH & MTBA	2018-10-01	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Yes
L8038	38	Mill Street	1	Between 1885 and 1888	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Russell Brick, fer blanc steeple roof, asphalt shingles, stone detailing and foundation	Tall 1 storey church; silhouette created by iconic tall center steeple and simple gable; faceted fer blanc steeple with pointed arch vents and iron cresting; pointed arch stained glass windows to sanctuary; pointed arch wood framed door with transom lite above window in tower; date stone reading "Presbyterian Church 1888;" fine brick detailing including corbelled arches over windows and doors, corbelled dentils, quatrefoils and decorative courses at top of the tower; buttresses with stone caps; gable roofs; rear addition with gable roof and segmentally-arched doorway within	Land purchased from W.Z. Helmer in 1885; originally built for the Presbyterian congregation who had outgrown their other church; St. Andrew's Presbyterian church merged with the St. Paul's Methodist church in 1925 to form St. Andrew's and St. Paul's United Church.	Landmark building visible from Concession Street bridge over the Castor River; iconic steeple is the tallest built structure within the Study Area; large property with large setbacks on all sides to accommodate parking lot, landscaped area and mature trees.	MTBA	2018-12-01		Yes
L8039	39	Mill Street	3	1970, 1974	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Canadian Government. A19865-219 [aerial photo]. 1967. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa	Metal roof, siding, stone veneer	2 storeys; bungalow attached to garage and inhabited upper level.	Currently unknown.	Backs onto Castor River; large lot with large front setback; mature trees.	MTBA	2018-12-01		Yes

L8043	43	Mill Street	1	c.1864; other sources show 1948	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Stone foundation, siding, wood trim, brick chimney	1 ½ storeys; side gable roof with central gable; variation of classic T-shaped plan "Ontario gothic cottage;" wood trim including exterior shutters; detailed brick chimney; said to be the only building in the Village constructed of cedar blocks.	Formerly owned by Dr. Joseph C Bass (physician) and Dr. Loux (descendent of one of the first settlers of the region).	Overlooks Castor River; wide yet shallow wedge-shaped lot which allows public views to the river; mature trees.	MTBA & KW	2018-10-10		Yes
L8044	44	Mill Street	1	1883	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Siding, asphalt shingles, wood trim	1 ½ storeys; L-shaped plan with gable roof and gable dormer; double hung windows; front porch with railing and columns supporting hipped roof; decorative wood trim including at top of front gable.	Currently unknown.	Medium front setback; contributes to its streetscape; mature trees.	MTBA	2018-12-01		Yes
L8048	48	Mill Street	1	1890	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Metal tile roof, siding, wood trim	2 storeys; L-shape plan; gable roof; large wrap-around porch with balustrade and slender columns supporting shed roof with small gable over entrance; gazebo with hipped roof integrated with porch; pairs of double-hung windows; wood trim.	Currently unknown.	Large front setback; white picket fence bordering sidewalk; contributes to its streetscape; mature trees.	MTBA	2018-12-01		Yes
L8052	52	Mill Street	1	1885	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Brick (likely Russell Brick), wood trim, pressed metal shingles, metal sheet roof	2 ½ storeys; gable roof; porch with elaborate "gingerbread" and balustrade; segmentally arched window openings with large contrasting window sills; arched, transom window over front door; fine craftsmanship shown in decorative brickwork; large bay window with hipped	Currently unknown.	Large property with large setbacks; contributes to its streetscape; mature trees.	MTBA, SL & CB	2018-10-04		Yes
L8056	56	Mill Street	1	1904	Russell Historical Society. "Russell House Tour" [walking tour script]. 2014.	Brick (likely Russell brick), metal roofing, wood trim, asphalt shingles, vinyl siding, stone sills and lintels	2 ½ storeys; side gable roof with large front gable; front porch with balcony above supported by wood columns; railings; decorative brackets supporting balcony roof; segmentally arched window openings; brick walls and chimney; small pre-1945 garage/outbuilding with wood siding.	One of three houses said to be the Presbyterian manse; the walking tour script from 2014 says that it was the Presbyterian manse until 1926 when it became the home of the United Church minister.	Prominent corner location; large property with large setbacks; mature trees.	MTBA, SL & CB	2018-10-04		Yes
L8064	64	Mill Street	1	c. 1860s; other sources show 1900	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988; Tweedsmuir History. Russell Village Women's Institute, organized December 1st, 1936. Edited by G. E. McCaffrey. Russell, 1967; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Metal roof, asphalt shingles, siding	2 storeys; gable roofs; L-shape plan; highly modified.	Built by John Mattice (mill owner and one of the first settlers); said to be the first frame house in the Village	Prominent corner lot; large front and side setbacks; mature trees.	MTBA	2019-03-01		Yes
L8068	68	Mill Street	3	1951	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. RCAF. S(30) RR2118 408(R) [aerial photo]. 1960.	Stone veneer siding, wood siding, concrete sills, asphalt shingles	1 storey; hipped roof with chimney; recessed entrance; small porch with metal balustrade; size and placement of windows; compact form.	Currently unknown.	Large front setback; mature trees.	MTBA	2018-12-01		Yes
L8071	71	Mill Street	4	1984	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; Ibid. 2002.	Brick, siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 ½ storeys; bellcast side gable roof with gabled dormers and chimney; two bay windows; recessed front entrance.	Currently unknown.	Backs onto Castor River; large wedge-shaped lot; Large front setback; contributes to its streetscape; mature trees.	MTBA	2018-12-01		Yes

L8072	72	Mill Street	1	1880	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Siding, wood trim, asphalt shingles	1 ½ storeys; front gable roof; porch with railing and columns supporting shed roof; small windows on upper floor; wood trim.	One of three houses said to be the Presbyterian Manse; according to W.E. Stanley, "the first [Presbyterian] manse, a frame house purchased from a Mrs. Kilbourn in 1874, is still standing..." This is consistent with the styles of architecture, fire insurance plans and location	Small front setback; contributes to its streetscape; mature trees.	MTBA	2018-12-01	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. ; Eastman Topographic Safety. A9558-8 [aerial	Yes
L8073	73	Mill Street	3	1960	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. RCAF. S(30) RR2118 408(R) [aerial photo]. 1960.	Brick, siding, asphalt shingles	1 storey; large shallow gable roof; L-shaped plan; size, shape and placement of windows.	Currently unknown.	Backs onto Castor River; large front setback; mature trees.	MTBA	2018-12-01		Yes
L8074	74	Mill Street	1	1915	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Display. "The Great Russell Fire." Keith Boyd Museum. Russell, Ontario. Accessed November 29, 2018. Eastman Topographic Safety.	Brick (likely Russell brick), stone/concrete lintels and sills, metal roof, wood trim	2 ½ storeys; hipped roof with dormers; front porch supported by brick columns; transom windows on main floor; symmetrical façade; large contrasting lintels and sills; brick walls and chimney.	One of three houses said to be the Presbyterian manse; previous house was destroyed by great fire of 1915 due to its location adjacent to the former blacksmith.	Large front setback; mature trees.	MTBA	2018-12-01	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Yes
L8075	75	Mill Street	1	1871	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Concrete block chimney, asphalt shingles, wood siding and trim	1 ½ storeys; T-shape plan typical of the "Ontario gothic cottage;" side gable roof with centre gable; wood siding and trim including decorative exterior shutters and "gingerbread;" side gable roof; centre gable with round arched window; arched entrance canopy.	Robert Hay (blacksmith); Dr. Proudfoot (first resident dentist of the Village).	Backs onto Castor River; small front setback; contributes to its streetscape; mature trees.	MTBA & KW	2018-10-01		Yes
L8077	77	Mill Street	1	1924	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety.	Brick (likely Russell Brick), pressed metal roof, wood trim	2 ½ storeys; hipped roof with dormers; brick walls and tall chimney; symmetrical front façade; front porch with hipped roof and central gable supported by slender columns; rear porch; large wood-framed windows with large contrasting lintels and sills; pressed metal roof.	Currently unknown.	Backs onto Castor River; large front setback.	MTBA	2018-12-01		Yes
L8078	78	Mill Street	4	Between 1945 and 1960; 1900 (former blacksmith site)	Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. ; RCAF. S(30) RR2118 408(R) [aerial photo]. 1960; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Metal roof, metal siding, wood balcony	Factors contributing to compatibility (not currently protected): 2 storeys; gambrel roof; balcony.	Former site of blacksmith and source of the great fire of 1915.	N/A	MTBA	2018-12-01	Display. "The Great Russell Fire." Keith Boyd Museum. Russell, Ontario. Accessed November 29, 2018.	Yes
L8081	81	Mill Street	2	1860	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Lap siding and board and batten siding, concrete foundation, asphalt shingles	1 ½ storeys with multiple additions; gable roofs; dormers with gable roofs; wood panel door; highly altered.	Originally owned by Dr. George Dickenson.	Backs onto Castor River; no front setback; small side setbacks; mature trees.	MTBA & KW	2018-10-01		Yes

L8083	83	Mill Street	2	Before 1908; other sources show 19402	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Siding, asphalt shingles	1 ½ storeys; gable roof and dormer window; compact form of original building.	Formerly owned by Russ Phair who operated many businesses here including ophthalmic dispenser, watchmaker, electrical and hair styling.	Backs onto Castor River; addition comes right to sidewalk (no front setback); small side setbacks; mature trees.	MTBA	2018-12-01	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Yes
L8085A	85	Mill Street	1	Shortly after 1861	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Concrete foundation, asphalt shingle, siding	Main building (fronting Mill Street): 2 storeys; gable roof; multiple additions; variety of sizes of windows including large storefronts.	Formerly John Duncan's cabinet and furniture shop; built and owned by William and Alec Craig.	Prominent street corner location within the village core; backs onto Castor River; no front or side setback; contributes to its streetscapes; mature trees. A smaller shop fronting Concession Street is located at the rear of this property, near the Concession Street Bridge (refer to Individual Property Evaluation L8085B for more information on this building).	MTBA & KW	2020-11-01		Yes
L8085B	85	Mill Street	2	?		Metal roof, siding	Secondary building (fronting Concession Street): 1 storey; small compact form; modified gable roof; two square windows on either side of front door; side porch overlooking Castor River;	Currently unknown.	Prominent street location on main thoroughfare near Concession Street Bridge; overlooks Castor River; no front setback; contributes to its streetscapes; mature trees. Located on the same property as the historic commercial/residential building (refer to Individual Property Evaluation L8085A for more information on this building).	MTBA	2020-11-01	N/A	Yes
L8092	92	Mill Street	1	1908	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Brick (likely Russell brick), wood siding	2 storeys; flat (low-slope) roof; decorative cornice; large storefront windows; wood storefront, siding and trim; size and location of windows and door on second floor; segmentally arched window openings on second floor; brick walls.	Built by the MacKerachers, owned by Cochrane and McKay until 1913 when leased to McArthur and Warner (who are said to have had "one of the best small town stores in Eastern Ontario").	Small front setback; prominent location in commercial core; contributes to its streetscape; large stairs running across the length of the front façade.	MTBA	2019-03-01		Yes
L8096	96	Mill Street	2	1890	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Vinyl siding, asphalt shingles, wood trim	1 ½ storeys; front gable roof; compact form; chimney; small gable canopy over front entrance supported by two wood columns; size and location of windows. (highly modified)	Currently unknown.	Medium front setback; contributes to its streetscape; mature trees.	MTBA	2019-01-01		Yes
L8097	97	Mill Street	4	2001	My Byward Condo. 97 Mill Street unit #2D [real estate listing]. Accessed January 2019; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Brick, asphalt shingles	Factors contributing to compatibility (not currently protected): 2 storeys; hipped roof with central gable; symmetrical façade; size and location of windows.	Currently unknown.	Backs onto Castor River and park; small front setback.	MTBA	2019-01-01		Yes
L8098	98-100	Mill Street	4	2009	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; City of Ottawa. GeoOttawa [aerial photo]. 2002. Accessed October 2019.	Vinyl/metal siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 2 storeys; gable and hipped roofs; small canopy over entrances.	Currently unknown.	Medium front setback.	MTBA	2019-01-01		Yes
L8101	101	Mill Street	1	c.1861	Historic plaque on building; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Stucco, asphalt shingles	2 storeys; wooden side door; timber stairs and garden wall; stucco finishing; wood framed windows; lattice built into north wall; north wall octagonal window on second storey; porch and arches	Property was formerly owned by many of the region's first settlers including: William Duncan, John Kelley and others. The house is associated with mill owner and MP William Craig whose family owned this house from 1862-1906. Craig Street is named after him.	Backs onto Castor River; large setbacks; mature trees.	MTBA, ML & AM	2018-10-10	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Yes
L8102	102-104	Mill Street	4	2008	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Vinyl/metal siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 2 storeys; gable and hipped roofs; small canopy over	Currently unknown.	Medium front setback.	MTBA	2019-01-01		Yes

L8106	106	Mill Street	2	1840	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Metal siding, stone veneer; asphalt shingles	1 ½ storeys; symmetrical front and side facades; canopy over front entrance; chimney (highly modified).	Said to be a former stopping place before the Palace Hotel/Russell House was built.	Small front setback; contributes to its streetscape.	MTBA, ML & AM	2018-10-10		Yes
L8108	108	Mill Street	2	1857	Wade, W. D. <i>Celebrating 150 Years at Russell House</i> . Ottawa: Commoners' Publishing Inc., 2007	Field stone, wood, brick, stucco	2 storeys; flat (low-sloped) roof; size, proportion of window openings on second floor indicating location of former hotel rooms; main entrance at centre of front façade.	James Kelley (original land owner in the Village; prominent business person in Russell and Vancouver); Joseph Payette (prominent community member); Bill Lineger (Ottawa Rough Rider football player). Note: Although the appearance has been significantly altered, this property is still of heritage significance due to its	Overlooks Castor River across street at front; small front setback; contributes to its streetscape.	MTBA	2018-10-01 update	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Yes
L8112	112	Mill Street	4	2004	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; City of Ottawa. GeoOttawa [aerial photo]. 2002. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Vinyl siding, asphalt shingles, wood trim	Factors contributing to compatibility (not currently protected): 2 storeys; side gable roof; porch with wood columns supporting hipped roof with central gable; balconies with wood balustrade and columns supporting gable roof.	Currently unknown.	Medium front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes
L8119	119	Mill Street	1	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Russell brick; wood trim, metal roof; concrete block foundation	2 ½ storeys; hipped roof with dormer and tall chimney; Russell brick; front porch with wood railings and ornate columns supporting a gable roof; large windows with contrasting lintels and sills; sunroom/conservatory at side of house with transom lites; two rear balconies overlooking the River.	Former property of Mr. Duncan, one of the first settlers in the Village.	Backs onto the Castor River at a prominent location on bend in the river; highly visible landmark as seen from the Concession Street Bridge.	MTBA, ML & AM	2018-10-10	Stanley, Wendell M. <i>From Swamp and Shanty</i> . Runge Press, 1988.	Yes
L8120	120	Mill Street	2	1890	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Wood, metal siding, brick, metal roof and asphalt shingles	2 storeys; wooden front porch; exterior access to basement; metal stairs, buff coloured brick chimney, octagonal front enclosed extrusion, dormer roof and gazebo roof over extrusion; 1 storey addition added in 2016.	The house was renovated in 1947 to accommodate the newly established mission of Our Lady of the Miraculous Medal (Catholic church). The chapel facilities were relocated in 1961 upon completion of a new church building on First Avenue.	Across street from Castor River.	MTBA, ML & AM	2018-10-10	Display. "The Great Russell Fire." Keith Boyd Museum. Russell, Ontario. Accessed November 29, 2018.	Yes
L8125	125	Mill Street	1	1890	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Wood siding, metal roof	1 ½ storeys; compact form; front gable roof; front porch with columns supporting shed roof; size and location of windows; wood siding	Currently unknown.	Backs onto Castor River; corner property with large setbacks; secluded location at a bend in the road; orientation to the side of the property reflects former street layout; mature trees.	MTBA, ML & AM	2018-10-10		Yes
L8126	126	Mill Street	3	1880	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Vinyl siding, asphalt shingles, concrete foundation	2 storeys; compact form; gable roof; chimney; size and location of windows.	Currently unknown.	Orientation reflect historic street alignment; medium front and side setbacks; wedge-shaped lot at bend in the road.	MTBA	2019-01-01		Yes

M7007	7	Main Street	3	1945	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; RCAF. S(30) RR2118 408(R) [aerial photo]. 1960. Canadian Government. A19865-219 [aerial photo]. 1967.	Vinyl siding, brick chimney, asphalt shingles, concrete foundation	1 ½ storeys; compact form; gable roofs; prominent chimney; front porch with railing and columns supporting shed roof.	Currently unknown.	Medium front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes
M7009	9-11	Main Street	4	2013	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; City of Ottawa. GeoOttawa [aerial photo]. 2002. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Metal roof, stone veneer, siding	Factors contributing to compatibility (not currently protected): 1 ½ storeys; side gable roof with multiple front gables; stone and wood tiered columns supporting canopy over main entrances; large windows.	Currently unknown.	Medium front setbacks.	MTBA	2019-01-01		Yes
M7010	8-10	Main Street	4	2005	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. City of Ottawa. GeoOttawa [aerial photo]. 2002. Accessed October 2018.	Vinyl siding, stone veneer, asphalt shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 1 storey; compact form; gable roofs.	Currently unknown.	Large front setback.	MTBA	2019-01-01		Yes
M7012	12	Main Street	3	Between 1967 and 1976	Canadian Government. A19865-219 [aerial photo]. 1967. ; City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Board and batten wood siding, concrete foundation, asphalt shingles	1 storey; low slope gable roofs slightly offset to create a sense of floating planes; size and placement of windows; articulated volumes; wood siding.	Currently unknown.	Large property with large setbacks; backs onto school grounds; mature trees.	MTBA, SL & CB	2018-10-04		Yes
M7015	15	Main Street	1	Between 1908 and 1945	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Wood siding and trim, asphalt shingles	1 ½ storeys; Dutch gable roof with chimney; wood siding; well-detailed wrap-around porch with wood balustrade and columns; wood trim including "gingerbread" detailing; compact form; bow window.	Currently unknown.	Medium setback.	MTBA	2019-01-01		Yes
M7018	18	Main Street	4	Between 1976 and 2002	City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Metal siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 storey; compact form; gable and hipped roof.	Currently unknown.	Backs onto school grounds; large front setback.	MTBA	2019-01-01		Yes
M7019	19	Main Street	4	Between 2009 and 2013	Google Streetview, 2009.; Ibid 2013	Metal Roof, board and batten wood siding, stone veneer	Factors contributing to compatibility (not currently protected): 1 storey; long side gable roof with two front gables.	Currently unknown.	Medium setback; corner lot.	MTBA	2020-11-01		Yes
M7024	24	Main Street	1	1890	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Vinyl siding, asphalt shingles, wood trim	1 ½ storeys; L-shape plan; gable roofs; large wrap-around porch with balustrade and columns supporting hipped roof; wood trim including "gingerbread" detailing; size and location of windows.	Currently unknown.	Prominent corner location; backs onto school grounds; medium front setback; contributes to its streetscape; mature trees.	MTBA	2019-01-01		Yes
N4088	1088	Concession Street	1	1914	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Brick (likely Russell brick), metal roof, "Boyd Block" concrete block foundation, concrete sills and lintels	2 ½ storeys; hipped roof with dormer windows; 1 storey bay window on front façade with conical roof; 2 storey bay window at the side with cantilevered gable roof; large projecting front entrance vestibule large windows with transoms, and hipped roof; size and location of windows with large contrasting lintels and sills; use of local materials.	Former funeral home of William C. Millar, undertaker.	Prominent location on main thoroughfare; large front setback; mature trees.	MTBA	2019-03-01		Yes

N4090	1090	Concession Street	3	1960	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. Canadian Government. A19865-	Vinyl siding, asphalt shingles	1 storey; side gable roof; front deck; bow window.	Currently unknown.	Large front setback; mature trees.	MTBA	2019-03-01		Yes
N4091	1091	Concession Street	3	1918	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Brick, vinyl siding, metal roof	2½ storeys; front gable roof; large porch with balustrade and columns supporting shed roof; size and location of windows; period storm windows.	Currently unknown.	Medium front setback; prominent location on main thoroughfare; contributes to its streetscape.	MTBA	2019-03-01		Yes
N4092	1092	Concession Street	1	1908; other sources show 1912	Private communication with owner; Municipal Property Assessment Corporation (MPAC) - Accessed April 2019.	Russell brick, metal roof, concrete foundations, wood trim	2 ¼ storeys; large well-proportioned front porch with ornate balustrade and two pairs of classical style Doric columns supporting large balcony; hipped roof with dormer windows; size, shape and location of window openings with large contrasting sills and lintels; stained glass window and oval shaped window; decorative wood trim including soffit brackets; Russell brick walls.	Built by the Canada Milk Products Company for its manager who operated the skim milk powder plant on a railway siding at the corner of Concession and what is now the Nature Trail.	Prominent location on main thoroughfare; small front setback; contributes to its streetscape.	MTBA	2019-01-01	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Yes
N4093	1093	Concession Street	2	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Vinyl siding, metal roof	2 storeys; front gable roof; bay window; wraparound porch; size and location of windows.	Currently unknown.	Medium front setback; prominent location on main thoroughfare; contributes to its streetscape.	MTBA	2019-03-01		Yes
N4094	1094	Concession Street	1	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada; Mikel, Robert. 2004. Ontario House Styles. Toronto: James Lorimer & Company Ltd., Publishers.	Russell Brick, wood trim, metal roof, concrete foundation	2 ½ story building; symmetric front façade; central dormers on hipped roof; porch with centre gable on shed roof square columns with capitals and brick bases support porch roof; half-sash windows on front façade; wood trim including soffit brackets; Russell brick walls and chimney; pre-1945 garage/outbuilding has front gable roof and wood siding fronting on Craig Street.	Currently unknown.	Large lot located at intersection of two prominent streets; small front setback; medium side setback; outbuilding with loft and hoist has frontage on intersecting street.	MTBA, KB & DM	2018-10-01	McIlwraith, Thomas. 1997. <i>Looking For Old Ontario</i> . Toronto: University of Toronto Press.	Yes
N4095	1095	Concession Street	2	1912	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Wood siding, metal roof	2 storeys; side gable roof; compact form; symmetrical façade; porch with large wood columns; wood siding; size and location of windows; chimney.	Currently unknown.	Medium front setback; prominent location on main thoroughfare; contributes to its streetscape; mature trees.	MTBA	2019-03-01		Yes

N4097	1097	Concession Street	4	1970	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945. City of Ottawa. GeoOttawa [aerial photo]. 1976. Accessed October 2018.	Brick, asphalt shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 1 storey; side gable roof.	Currently unknown.	Large front setback; prominent location on main thoroughfare.	MTBA	2019-03-01		Yes
N4098	1098	Concession Street	2	1900	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Metal chimney and roof, wood porch and window trim, vinyl siding	2 storeys; porch with shed roof and wood columns; size and location of windows; gable roof; octagonal window at side.	Currently unknown.	Prominent corner location on main thoroughfare; small front setback; small exterior side setback; Russell Brick integrated with landscaping; contributes to its streetscape.	MTBA, KB & DM	2018-10-01		Yes
N4099	1099	Concession Street	1	1913	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	"Boyd Block" decorative concrete block, wood trim	2 ½ storeys; hipped roof with dormer; symmetrical façade; porch; unique wood balcony with wood balustrade; polychromatic "Boyd Block" artistic concrete block construction with contrasting sills, lintels and quoins and 2 groups of 3 decorative concrete pedestalled columns, and balustrade; wood cornices soffit brackets and dentils; size and location of windows	Said to be former meeting place of Russell Village Women's Institute.	Landmark building at a prominent street corner on axis with main thoroughfare into the Village; medium front setback provides a small front yard and includes balanced landscaping at front and side yards; mature trees.	MTBA, KB & DM	2018-10-01		Yes
N4100	1100	Concession Street	1	1914	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Russell brick, metal roof, concrete foundation, wood trim	2 ½ storeys with; hipped roof with front dormer; front porch with wood balustrade and wood columns supporting shed roof; heavy contrasting window sills and lintels; size and arrangement of windows (ie. Roughly symmetrical front); Russell brick walls on all sides visible from street.	Currently unknown.	Prominent location on main thoroughfare; medium front setback; mature trees.	MTBA	2019-01-01		Yes
N4101	1101	Concession Street	1	1900	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Wood siding, frame and porch, metal roof	2 ½ storeys; gable roof; L-shape plan; two storey bay window; wrap-around porch with decorative balustrade and gingerbread; decorative wood detailing including: siding, trim, gingerbread, window frames, porch, columns, balustrade; bright multi-coloured paint finish which highlights heritage detailing.	Currently unknown.	Located on a prominent corner on the main thoroughfare; medium front setback; small exterior side setback and large interior side setback; well-known in the community.	MTBA, KB & DM	2018-10-01	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Yes
N4102	1102	Concession Street	2	1905	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Vinyl lap and shingle siding, asphalt shingles and pressed metal roof, wood trim	2 storeys; compact form; front gable roof; wrap-around porch with columns supporting hipped roof with central gable; size and location of windows; pressed metal roof; wood trim.	Currently unknown.	Prominent location on main thoroughfare; small front setback; mature trees.	MTBA	2019-01-01		Yes

N4103	1103	Concession Street	2	1909	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Siding, metal roof, wood trim	2 storeys; hipped roof; large wrap-around porch with square columns supporting hipped roof; size and location of windows; wood trim.	Currently unknown.	Located on main thoroughfare; medium front setback and large side yard; mature trees.	MTBA	2019-01-01		Yes
N4104	1104	Concession Street	1	c.1875	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Russell Brick, wood trim, metal roof	1 ½ storeys; symmetrical front façade; segmental and round arched openings; side gable roof with front gable; wood trim including "gingerbread" detailing; traditional wood windows and storms; traditional wood outbuilding (pre-1945) at rear of building, minimally visible from public realm.	Second oldest remaining building in the village; John Hall and his son Garland were the printers of the Russell Ledger until it ceased publication in 1942. From 1942-1974 former editor (Garland) ran a print shop in the back room.	Prominent location near commercial core; backs onto school yard; has a wooden addition as well as an old wood barn in the backyard; Russell Brick integrated into landscaping.	MTBA, KB & DM	2018-10-01, updated	Private Communication with owner, October 10, 2018	Yes
N4106	1106	Concession Street	4	N/A	N/A	N/A	Factors contributing to compatibility (not currently protected): None. (A two storey mixed use commercial/residential building is under construction on this lot.)	Currently unknown.	Prominent location on main thoroughfare in commercial core; backs onto school grounds.	MTBA	2018-12-01		Yes
N4107	1107	Concession Street	2	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Metal roof, vinyl siding, wood trim, wood porch	2 stories; compact form; symmetrical facade; hipped roof; front porch with wood balustrade and columns supporting a hipped roof; double hung windows.	Currently unknown.	Prominent location near commercial core; medium setback providing small front yard; large side yard.	MTBA, KB & DM	2018-10-01	McIlwraith, Thomas. 1997. <i>Looking For Old Ontario</i> . Toronto: University of Toronto Press.	Yes
N4108	1108	Concession Street	4	2000	Building Permit information	Siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 storey; gable roof.	Currently unknown.	Mature trees; contributes to its streetscape.	MTBA	2018-10-01		Yes
N4109	1109	Concession Street	2	1900	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M. From Swamp and Shanty: The History of Russell Village and the Western Part of Russell Township, 1827-1987:	Wood frame, wood trim, vinyl siding, stone veneer siding, metal balcony and railing, asphalt shingles	2 ½ stories; porch with columns with angled struts supporting the balcony; double hung windows; cross gabled roof.	Associated with shoemakers Hiram Pelton and Sarsfield York who operated their business here between 1864 and 1912, although the house at this time was owned by Lorne Honey.	Situated on a prominent corner in the downtown core; small front setback.	MTBA, KB & DM	2018-10-01		Yes
N4111	1111	Concession Street	3	Between 1908 and 19	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Wood frame, vinyl siding, metal railing, asphalt shingles	2 storeys; gable roof; porch with columns supporting hipped roof with gable.	Currently unknown.	Situated on a prominent corner in the downtown core, small front setback.	MTBA	2020-11-01	N/A	Yes
N4112	1112	Concession Street	4	2011	Building Permit information	Stone veneer, stucco	Factors contributing to compatibility (not currently protected): 1 storey; compact form.	Currently unknown.	Situated on a large corner lot on main thoroughfare in the commercial core.	MTBA	2018-10-01		Yes
N4113	1113	Concession Street	1	1883	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press,	Siding, asphalt shingles, wood trim	2 storeys; gable roof; size and location of windows; shutters.	Formerly Helmer's Barber shop, which was purchased by Fred Loucks (descendant of early settler Elisha Loucks) who ran his own barber shop for nearly	Prominent location on main thoroughfare; small front setback; contributes to its streetscape; small-scale street-oriented retail.	MTBA, LL & TH	2018-10-15		Yes

N4115	1115	Concession Street	2	1900	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1900." [aerial photo]. 1900.	Lap siding and board and batten wood siding, metal roof, brick chimney, concrete foundation	2 storeys; compact form; gable roof; size and location of double hung windows; chimney.	Location of the second barber shop of Fred Loucks (descendant of early settler Elisha Loucks) who was in the business for nearly 80 years.	Prominent location on main thoroughfare; small front setback; contributes to its streetscape; small-scale street-oriented retail.	MTBA, LL & TH	2018-10-15	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Yes
N4116	1116	Concession Street	4	1976	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976.	Brick, glass	Factors contributing to compatibility (not currently protected): Compact form.	Currently unknown.	Located on a prominent corner on the main thoroughfare in the commercial core.	MTBA	2018-10-01		Yes
N4119	1119	Concession Street	2	1900	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press,	Stone veneer, metal siding, lap siding, metal roof	2 storeys; gable roofs; bay window; casement windows; unique form created by joining two separate buildings with a central addition after 1970.	References the evolution of the historic residential street by maintaining the scale and form of residential in a functioning commercial property.	Prominent location on the main thoroughfare; small front setback; contributes to its streetscape; small-scale street-oriented retail.	MTBA, LL & TH	2018-10-15		Yes
N4120	1120	Concession Street	3	Between 1960 and 1967	RCAF. <i>S(30) RR2118 408(R)</i> [aerial photo]. 1960.; Canadian Government. <i>A19865-219</i> [aerial photo]. 1967.	Brick, asphalt shingles, siding	1 storey; compact form; hipped roof; operable transom windows; size and shape of windows	Postal services since 1960s.	Small front setback; small garden and flag pole in front of building; contributes to its streetscape.	MTBA	2018-10-01		Yes
N4122	1122	Concession Street	1	1874 to 1875	MHBC Planning, Urban Design & Landscape Architecture. Final Report: Russell Land Registry Office Conservation Plan. 2013.	Russell brick, asphalt shingles	1 storey; front gable roof; symmetrical front façade; semi-circular arched windows and door openings with large contrasting key stones; brick pilasters with contrasting capitals; decorative brickwork including arcading, dentils, corbelling; surviving cast iron window grills, window hoods and sills; signage on front gable: "County Registry Office".	Associated with the provincial government's role in land registration; built to a design developed by the Department of Public Works in 1868; fireproof construction evidenced by the fact that it survived the Great Russell Fire of 1915 (with the exception of its timber and slate roof); constructed by Thomas Russell.	Prominent location on a highly visible intersection between two major thoroughfares; small front setback; status as a freestanding building (rather than the standard provincial pattern which integrates a courthouse and jail).	MTBA	2019-04-03		Yes
N4126	1126	Concession Street	1	1915	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Brick (likely Russell Brick), asphalt shingles, wood trim, wood framed windows; stone lintels/sills	2 ½ storeys; eclectic mix of roof forms including mansard, gambrel, gable, shed and hipped; front porch with brick and wood columns supporting decorative pediment; porch and columns at side entrance; brick walls; wood trim; two storey bay window; oval windows with decorative brickwork; double hung wood frame windows with wood storm windows; oriel window; large contrasting lintels and sills.	Currently unknown.	Prominent corner location on the main thoroughfare at the heart of the commercial core; relatively large setbacks.	MTBA	2018-12-01		Yes
N4127	1127	Concession Street	1	1910	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Russell brick, concrete foundation, sandstone and concrete lintels, vinyl siding	2 ½ storeys; Russel brick on original building; double hung windows with heavy lintels; gable roofs; two-bay garage.	Bernard Murray (tinsmith), Don MacArthur who ran the General Motor's dealership.	Prominent corner location on the main thoroughfare; small front and side setbacks.	MTBA, LL & TH	2018-10-01		Yes
N4128	1128	Concession Street	4	Between 1976 and 2002, likely late 1980s or early 1990s.	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; <i>ibid.</i> 2002.	Brick, concrete foundation	Factors contributing to compatibility (not currently protected): 2 storeys; flat (low-slope) roof; large storefront windows; projecting large rectangular "bay" windows; brown brick with buff brick accents at cornice, lintels and sills.	Currently unknown.	Prominent corner location on the main thoroughfare; contributes to its streetscape; small front setback.	MTBA, LL & TH	2018-10-15		Yes

N4129	1129	Concession Street	1	1915	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Brick (likely Russell Brick), decorative concrete block (likely Boyd Block), metal roof	Tall 1 storey; Dutch-type front façade with gable roof behind; 1915 A.D. date stone in front gable and 5915 A.L. date stone in rear wall; spherical finials; stone door surround with classical detailing of the Doric order including pediment with "Square and Compasses" symbol; central chimney; size and symmetrical location of windows with large contrasting lintels and sills; brick and concrete block walls.	Associated with the Grand Lodge of Canada in the Province of Ontario; the Russell branch was founded in 1906 by many well-known community residents including Dr. Proudfoot, William MacEwan, and Dr. MacDougall	Small front setback; contributes to its streetscape; key institutional property.	MTBA	2018-10-01		Yes
N4131	1131-1133	Concession Street	1	c.1915	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Russell brick, wood trim	Built in multiple phases; brick walls and cornices with corbelled brick dentils; large wood-framed storefront windows with large plate glass windows; wooden cornices; wood panelling above and below windows; size and location of windows; window openings with heavy lintels and sills; recessed entrance at corner splayed at 45° with column.	Built just after the fire of 1915 ravaged this site	Prominent corner location on main thoroughfare; highly visible location; built right to the sidewalk (no front setback); defines the commercial character and streetscape of Village Core.	MTBA	2018-10-01		Yes
N4135	1135	Concession Street	4	Between 1976 and 2002	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Metal siding and red brick, asphalt shingle roofing	Factors contributing to compatibility (not currently protected): Long 1 storey; gable roof with two intersecting gables.	Currently unknown.	Overlooks Duncanville Park and the Castor River; prominent location at the intersection of two major streets.	MTBA, LL & TH	2018-10-01		Yes
N4141	1141	Concession Street	1	c. 1970s	Canadian Government. A19865-219 [aerial photo]. 1967. City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976.	N/A	N/A	The Village of Russell was formerly known as Duncanville [Duncansville] which was named after John Duncan, one of the first settlers in the area.	Wide open views of Castor River; only public access to Castor River in the Study Area; accessible from Concession Street and Mill Street; mature trees; key public property.	MTBA	2018-10-01	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988. H. Belden & Co. <i>Illustrated Historical Atlas of the Counties of Stormont, Dundas and Glengarry, Ontario</i> . Toronto: H. Belden & Co. 1879	Yes
N4144	1144	Concession Street	1	1920	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019. Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Stained glass window, metal roof, vinyl siding, wood detailing, brick column piers	2 storeys; hipped roof; symmetrical 3 bay front façade with central door; size and location of windows; stained glass window; porch; wood trim; brick and wood columns; hipped roof.	Currently unknown.	Backs onto the Castor River; located at a prominent street corner on the main thoroughfare; medium front setback, small side setback and large rear yard setback; mature trees.	MTBA, CW & KM	2018-10-01		Yes
N4145	1145	Concession Street	1	1908	Municipal Property Assessment Corporation (MPAC) - Accessed April 2019; Russell Village Woman's Institute. A Snapshot of Russell 2010. Russell: Tina & Company, 2013.	Russell Brick, wood trim and windows	2 storeys; Russell brick walls; flat (low-slope) roof with deep soffits; oriel window; double height square bay with small windows; prominent wood detailed cornices at roof and bay tops; segmental arch window openings; casement windows and storm windows; large contrasting window sills; well-detailed front porch with balcony above; balanced asymmetrical façade.	Hayes Family (original owners); MacEwan family (Mrs. MacEwan was President of the Women's Institute)	Prominent location on main thoroughfare and aligned with intersecting street; side of property fronts the Castor River; visible from Duncanville Park; medium front setback; contributes to its streetscape; mature trees.	MTBA	2018-10-01	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Yes
N4146	1146	Concession Street	2	1971	Russell Historical Society. Keith M. Boyd Museum: History of the Museum.	metal siding, asphalt shingles	1 storey; modified gable roof; large rectangular form, three garage doors, two murals – one illustrating a historic train on the New York Central Railway and the other the horse-drawn "fire truck" that quenched the great Russell fire of 1915.	Built by volunteer firefighters and occupied by them until 2005; part of the Russell Historical Society's Keith Boyd Museum.	Prominent corner location on main thoroughfare; medium front and side setbacks; adjacent to the Keith Boyd Museum's Church Building; backs onto the cemetery; key public property.	MTBA	2020-11-01	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Yes
N4147	1147	Concession Street	4	After 2002	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 2002. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Brick, asphalt shingles, metal louvers, copper finial	Factors contributing to compatibility (not currently protected): 1 storey utility building, compact form, hipped roof with gable, copper finial/vent.	Currently unknown.	Large setback.	MTBA	2018-12-01		Yes

N4150	1150	Concession Street	1	1856	Russell Village Woman's Institute. <i>A Snapshot of Russell 2010</i> . Russell: Tina & Company, 2013.	Wood siding, pressed metal roof	Tall 1 storey; pointed arch window and door openings; gothic window muntin pattern, double hung windows; simple gable roof; simple geometric form; minimal external detailing; horizontal shiplap siding; 12-paneled wood front doors.	Oldest surviving public building in Russell Township; associated with its previous uses as St. Mary's Anglican Church and then the Baptist Church; associated with Keith M. Boyd (prominent community member and museum founder).	Prominent corner location on main thoroughfare; previously located on Second Avenue and then Castor Street and then South Russell Road (current location); medium depth front and side setbacks; contributes to its streetscapes; backs onto cemetery; mature trees; railcar from brick pit on display in side yard; key public	MTBA	2018-10-01	Stanley, Wendell M. From Swamp and Shanty. Ottawa: Runge Press, 1988.; Russell Historical Society. Keith M. Boyd Museum: History of the Museum.	Yes
N4152	1152	Concession Street	2	Between 1908 and 1918	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.; Kyles, Shannon. "Ontario Architecture." Edwardian (1890-1916), 2016. http://www.ontarioarchitecture.co	Brick (likely Russell Brick), metal roof, wood trim	2 ½ storeys; hipped roof with dormer window; porch with balustrade and tiered wood and brick columns; brick walls and chimney; large, contrasting lintels.	Currently unknown.	Located on a prominent street corner; large front setback; medium exterior side setback; contributes to its streetscape.	MTBA, CW & KM	2018-10-10		Yes
N4153	1153	Concession Street	1	1870	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Russell Brick, stucco, pressed metal and standing seam roof	2 storeys; well-balanced, symmetrical façade divided into 5 bays; ground floor with central front entrance and 2 windows on either side; 2 chimneys symmetrically arranged on the end walls; Russell brick walls (hidden); pressed metal roof; side gable roof.	Former home and offices of Doctor MacDougall and later Doctor Kinnaird; built by James Keays (among the first settlers to own land in the area and prominent community member, teacher, politician)	Located on a prominent street corner on the main thoroughfare; small front setback; medium side setback; mature trees.	MTBA	2018-12-01		Yes
P9011	11	Parallel Street	4	Between 1967 and 1976	Canadian Government. <i>A19865-219</i> [aerial photo]. 1967.; City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Vinyl siding, asphalt shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 1 ½ storeys; gable and shed roofs; deck with wood balustrade.	Currently unknown.	Corner property; large front and side setbacks.	MTBA	2019-01-01		Yes
P9012	12	Parallel Street	2	Between 1908 and 1945	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Aluminum siding, pressed metal roof, wood trim	2 storeys; compact form; hipped roof; front porch with wood balustrade and columns supporting balcony above; size and location of windows.	Currently unknown.	Medium front setback; mature trees.	MTBA	2019-01-01		Yes
P9014	14	Parallel Street	2	Between 1908 and 1945	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Pressed metal roof, vinyl siding, wood trim	2 storeys with 1 storey addition; hipped roofs; enclosed front porch/sunroom with continuous transom lights and hipped roof; wood trim; highly modified.	Currently unknown.	Corner property; medium front setback; mature trees.	MTBA	2019-01-01		Yes
P9027	27	Parallel Street	3	Between 1960 and 1967	RCAF. <i>S(30) RR2118 408(R)</i> [aerial photo]. 1960.; Canadian Government. <i>A19865-219</i> [aerial photo]. 1967.	Yellow vinyl siding, wood trim, asphalt shingles, brick	1 storey; gable roof; sunroom; bay window; decorative front door; chimney; compact form; separate garage.	Currently unknown.	Backs onto school grounds; medium front setback.	MTBA, SL & CB	2018-10-04		Yes
R2101	101	Castor Street	4	Between 1967 and 1976	Canadian Government. <i>A19865-219</i> [aerial photo]. 1967.; City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Brick, asphalt shingles, wood trim, concrete foundation.	Factors contributing to compatibility (not currently protected): 1 storey; gable roof extending over front porch; carport; balustrade and columns; bay window.	Currently unknown.	Located on prominent street corner; across the street from the Castor River	HH & MTBA	2018-10-01		Yes
R2107	107	Castor Street	3	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Vinyl siding, asphalt shingles	1 ½ storeys; front gable roof with two narrow side gables; size and placement of windows; compact form.	Currently unknown.	Backs onto school grounds; entrance oriented to side of property; mature trees.	MTBA	2019-01-01		Yes
R2111	111	Castor Street	4	Between 1976 and 2002	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; <i>ibid</i> . 2002.	Vinyl siding, asphalt shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 1 storey; irregular massing with gable roofs; large windows with shutters; small front deck with balustrade.	Currently unknown.	Backs onto school grounds; large front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes
R2115	115	Castor Street	2	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Vinyl siding, asphalt shingles	1 ½ storeys; L-shape plan with gable roof and additional front gable; front porch with columns supporting shed roof.	Currently unknown.	Backs onto school grounds; small front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes

R2119	119	Castor Street	3	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Wood siding, metal roof, wood trim	1 ½ storeys; compact form; combination dual slope roof with large front overhang over porch; log columns; wood siding and trim.	Currently unknown.	Backs onto school grounds; small front setback.	MTBA	2019-01-01		Yes
R2122	122	Castor Street	4	Between 1976 and 2002	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; <i>ibid.</i> 2002.	Brick, metal roof, wood trim, concrete foundation	Factors contributing to compatibility (not currently protected): 2 storeys; side gable roof; small front porch with shed roof; bay window.	Currently unknown.	Medium front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes
R2123	123	Castor Street	3	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Vinyl siding, asphalt shingles	2 storeys with 1 storey addition; compact form; front gable roof; front porch with balustrade and columns supporting hipped roof.	Currently unknown.	Backs onto school grounds; large front setback.	MTBA	2019-01-01		Yes
R2127	127	Castor Street	1	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Vinyl siding, metal roof, wood trim	1 ½ storeys; L-shape plan with gable roofs and additional front gable; entrance with columns supporting small gable roof; porch with balustrade and columns supporting shed roof; wood trim including gingerbread detailing; size and placement of windows.	Currently unknown.	Backs onto school grounds; small front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes
R2131	131	Castor Street	3	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Asphalt shingle roof, stone veneer, stucco, vinyl siding	1 ½ storeys; L-shape plan; gable roofs; (highly modified).	Currently unknown.	Backs onto school grounds; medium front setback.	MTBA	2019-01-01		Yes
R2139	139	Castor Street	1	Between 1885 and 1887	Stanley, Wendell M., <i>From Swamp and Shanty</i> . Ottawa: Runge Press, 1988.	Russell brick, metal roof, wood windows, doors and trim.	Tall 1 storey; gable roofs; Russell brick walls; wood windows, doors and trim; brick pointed arch window and door openings; period wood storm windows; stained glass windows from Montreal including large window at east façade comprised of three lancets and a rose window; tower with circular openings for ventilation (note that the belfry and bell were removed in 2013).	Building constructed by church members donating labour and materials; associated with the Anglican Diocese of Ottawa; Bishop Hamilton (the first bishop) and his brother who donated the stained glass windows; church bell from the Roman Catholic Church of Embrun.	Prominent corner location; small front and side setbacks.	MTBA	2019-01-01	Google Street View	Yes
R2143	143	Castor Street	2	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Aluminum siding, stone veneer, pressed metal roof	1 ½ storeys; L-shape plan typical of the "Ontario gothic cottage;" gable roof with dormer; porch with balustrade and shed roof.	Currently unknown.	Prominent corner location; small front and exterior side setbacks; contributes to its streetscape; mature trees.	MTBA	2019-03-01		Yes
R2148	148	Castor Street	3	Between 1967 and 1976	Canadian Government. <i>A19865-219</i> [aerial photo]. 1967. ; City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/	Brick, siding, asphalt shingles	1 ½ storeys; large front gable roof; large front windows; recessed single-car garage with decorative brickwork.	Currently unknown.	Medium front setback; contributes to its streetscape; mature trees	MTBA	2018-12-01		Yes
R2151	151	Castor Street	1	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Metal roof, siding, brick chimney, wood trim	1 ½ storeys with 1 ½ storey addition; L-shape plan; gable roofs; wood trim, balustrade and columns; size and location of hung windows; large wrap-around porch with shed roof and gable over entrance and integrated gazebo with hipped roof (note this was added in 2018 and while not of heritage value, it is a positive contribution to the streetscape).	Currently unknown.	Large property with small front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes

R2155	155	Castor Street	4	Between 1976 and 2002	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; ibid. 2002.	Vinyl siding, asphalt shingles, wood trim	Factors contributing to compatibility (not currently protected): 2 storeys; gable roofs; bay window.	Currently unknown.	Large front setback.	MTBA	2019-01-01		Yes
R2158	158	Castor Street	4	Between 1976 and 2002	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; ibid. 2002.	Siding, asphalt shingles	Factors contributing to compatibility (not currently protected): 1 ½ storey; compact form.	Currently unknown.	Medium setbacks	MTBA	2018-12-01		Yes
R2159	159	Castor Street	1	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Wood and stucco half-timbered siding, board and batten wood siding, asphalt shingles, wood trim	1 ½ storeys; compact form; front gable roof; front porch with wood balustrade and columns supporting a shed roof; size and location of windows; wood and stucco half-timbered siding.	Currently unknown.	Small front setback; mature trees; contributes to its streetscape.	MTBA	2019-01-01		Yes
R2163	163	Castor Street	3	Between 1908 and 1945	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Siding, metal roof, metal trim	2 storeys; compact form; front gable roof; front porch with balustrade and columns supporting hipped roof.	Currently unknown.	Small front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes
R2166	166	Castor Street	3	Shortly after the fire of 1915	Stanley, Wendell M., From Swamp and Shanty. Ottawa: Runge Press, 1988.	Siding, metal roof	1 storey; front gable roof; compact form.	Former commercial bakery of Harry Cordell (one of Russell's leading sports figures) which served the Village and surrounding areas until the late 1940s.	Entrance of house faces side of property; small front setback.	MTBA	2018-12-01		Yes
R2182	182	Castor Street	4	Between 1976 and 2002	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; ibid. 2002.	Metal and brick siding, metal roof	Factors contributing to compatibility (not currently protected): 1 storey; long side gable roof projecting over walkways.	Currently unknown.	Prominent location on main thoroughfare in commercial core.	MTBA	2018-12-01		Yes
R2183	183	Castor Street	4	Between 1976 and 2002	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; ibid. 2002.	Stone veneer, metal roof, siding	Factors contributing to compatibility (not currently protected): Compact form; gable roof; two large garage doors.	Currently unknown.	Large lot at a prominent intersection of two thoroughfares.	MTBA	2018-12-01		Yes
R2191	191	Castor Street	4	Between 1976 and 2002, likely early 1990s	City of Ottawa. <i>GeoOttawa</i> [aerial photo]. 1976. Accessed October 2018. http://maps.ottawa.ca/geoOttawa/ ; ibid. 2002.	Brick walls	Factors contributing to compatibility (not currently protected): 2 storeys; brown brick with buff brick accents at quoins, lintels and soldier courses; size and location of windows; flat (low slope) roof; basic commercial architectural composition is very compatible with traditional commercial village street.	Currently unknown.	Somewhat contributes to its streetscape.	MTBA, LL & TH	2018-10-15		Yes
R2195	195	Castor Street	3	Between 1908 and 1945	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945.	Vinyl siding, asphalt shingles	1 ½ storeys; compact form of original house; gable roofs. (highly altered)	Currently unknown.	Prominent corner location on main thoroughfare; medium front setback.	MTBA	2019-01-01		Yes
R2196	196	Castor Street	2	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Aluminum siding, asphalt shingles, concrete foundation	2 storeys; compact form; front gable roof; small front porch with balustrade and wood columns supporting gable roof; additional side porch with balustrade and wood columns supporting shed roof; size and location of windows.	Currently unknown.	Prominent location on main thoroughfare; small front setback.	MTBA	2019-01-01		Yes

R2203	203	Castor Street	2	Between 1908 and 1945	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada. ; Eastman Topographic Safety. A9558-8 [aerial photo]. 1945	Vinyl siding, asphalt shingles, wood trim	2 storeys; compact form; side gable roof; symmetrical front façade; front porch with balustrade and columns supporting hipped roof; size and location of windows.	Currently unknown.	Prominent corner location on main thoroughfare; medium front setback; contributes to its streetscape.	MTBA	2019-01-01		Yes
R2204	204	Castor Street	4	1978-1979	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Metal siding (white and brown), shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 2 storeys; gable/mansard roof; large patio doors opening onto balconies; canopy roof over main entrance;	Built by Rejean Paquette, Chantal Development, on the former site of Dance Hall built by Mr. Albert Cousineau in 1950.	On main thoroughfare near village core; set back from street to provide small front yard.	MTBA, ML & AM	2018-10-10		Yes
R2212	212	Castor Street	4	Between 1960 and 1967	RCAF. S(30) RR2118 408(R) [aerial photo]. 1960.; Canadian Government. A19865-219 [aerial photo]. 1967.	Brick, asphalt shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 1 storey; long side gable roof; recessed entrance; bay window.	Currently unknown.	Large front setback.	MTBA	2019-01-01		Yes
R2215	215	Castor Street	1	Before 1908	Goad, Chas. E. "Fire Insurance Plan of Russell, Ontario, September 1908." MIKAN 3835872, Library and Archives Canada.	Siding, asphalt shingles, wood trim	1 ½ storeys with 1 ¼ storey addition; front gable roof; compact form; wrap-around porch with wood columns supporting hipped roof; wood trim including "gingerbread" detailing; French doors; double hung wood windows, likely original.	Currently unknown.	Prominent location on thoroughfare; medium front setback.	MTBA	2019-01-01		Yes
R2220	220	Castor Street	4	Between 1960 and 1967	RCAF. S(30) RR2118 408(R) [aerial photo]. 1960.; Canadian Government. A19865-219 [aerial photo]. 1967.	Brick, asphalt shingles, concrete foundation	Factors contributing to compatibility (not currently protected): 1 storey; gable roof; recessed entrance; bay window; two single car garages with windows; metal transom panels above garage doors.	Currently unknown.	Large front setback.	MTBA	2019-01-01		Yes